

TIRO

RETIRO

BARRICAS NUEVAS

RECOMENDACIONES DE USO



- Revisar que no se presenten daños provocados durante el transporte.
- No retirar el envoltorio protector (film plástico y cartones) hasta el momento de su utilización.



- Humedad ambiente constante de entre 70 y 85%.
- Ambiente aislado con temperatura de 12 a 15°C (54 a 59°F).



- Protegido de rayos solares.
- Aislado de fuentes externas de contaminación.
- Sobre soportes (racks, pallets, plataformas).



- Retirar los envoltorios protectores.
- **Hidratación con Agua Fría:** con la barrica en forma horizontal llenar completamente con agua libre de cloro. Colocar tapón y dejar el agua por 7 a 8 horas.
- **Hidratación con Agua Caliente:** con la barrica en forma vertical, llenar con 20 a 30 litros de agua temperada (70 a 80°C; 158 a 176°F) y colocar tapón. Dejar 3 o 4 horas por cada fondo.



- Agitar la barrica unos minutos para que el agua recubra completamente el interior.
- Vaciar la barrica y dejar secar boca abajo por al menos 30 minutos para asegurarse que no queden restos de agua. Si durante este proceso es evidente la presencia de alguna filtración, y éste persiste, comunicarse con nuestras oficinas. La barrica esta lista para su utilización.



Importante:
Utilizar agua libre de cloro para la hidratación de la barrica.

WWW.TNCOOPERS.COM

10 cm

NEW BARRELS

PREPARATION & MAINTENANCE



- Check for possible damage produced during transportation.
- Do not remove protective wrapping (plastic film and cardboard) until the moment of its use.



- Constant ambient humidity between 70 and 85%.
- Insolated ambience with a temperature from 12 to 15° C (54 to 59°F).



- Protection from the sun's rays.
- Isolation from external sources of pollution.
- Rack support (racks, pallets, platforms).



- Remove protective wrappings.
- **Cold-water Hydrating:** with cask horizontally, completely fill with chlorine-free water. Place the tap and keep the water for 7-8 hours.
- **Hot-water Hydrating:** with cask vertically, fill with 20-30 liters of temperature water (70 to 80°C; 158 to 176°F) and place the tap. Keep for 3-4 hours per end.



- Agitate and stir the cask for several minutes so the water can completely cover its interior.
- Empty the cask and let it dry up-side down for at least 30 minutes to make sure that there are no traces of water left. If during this process there's and evident presence of any leakage, and it remains, you should contact our offices. The cask is now ready to be used.



Important:
Use chlorine-free water for hydrating the cask.

WWW.TNCOOPERS.COM

15,5 cm



HOMO
&
ZEGERS
DISEÑO

CLIENTE TN COOPERS

CONTENIDO TARJETA CUIDADOS BARRICAS (ING-ESP)

TAMAÑO 10 x 15,5 cm

FECHA 24 FEBRERO 2020

COLORES DE REFERENCIA



PANTONE 4515 C (C30 - M29 - Y64 - K10)
PANTONE BLACK C (C0 - M0 - Y0 - K90)